

F500164

12

NSWC TR 81-327

AD A130203

SAFETY EVALUATION OF "PHOTO FINISH"

BY R. F. BIS D. L. WARBURTON C. A. FREEMAN G. F. HOFF L. A. KOWALCHIK
M. E. DEGRABA E. LANIER J. H. BRUCE S. H. HAIRFIELD

RESEARCH AND TECHNOLOGY DEPARTMENT

3 NOVEMBER 1981

Approved for public release, distribution unlimited

DTIC FILE COPY



NAVAL SURFACE WEAPONS CENTER

Dahlgren, Virginia 22448 • Silver Spring, Maryland 20910

DTIC
ELECTE
JUL 5 1983
S B D

83 07 01 005

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NSWC TR 81-327	2. GOVT ACCESSION NO. DD-1130-203	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) SAFETY EVALUATION OF "PHOTO FINISH"		5. TYPE OF REPORT & PERIOD COVERED FINAL
		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) R. F. Bis, D. L. Warburton, C. A. Freeman, G. F. Hoff, L. A. Kowalchik, M. E. DeGraba, E. Lanier, J. H. Bruce, S. H. Hairfield		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS Naval Surface Weapons Center (Code R33) White Oak Silver Spring, MD 20910		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS 0;
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE 3 November 1981
		13. NUMBER OF PAGES 29
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release, distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Lithium Battery Safety heating Li/So ₂ batteries short circuit by-passed fuses forced discharge		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Li/So ₂ batteries are used to provide power for an air deployable expendable store "Photo Finish". This report presents results of a test program to determine if the system is safe for fleet use.		

DD FORM 1 JAN 73 1473


EDITION OF 1 NOV 65 IS OBSOLETE
S/N 0102-LF-014-6601

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)



UNCLASSIFIED


SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

FOREWORD

Li/SO₂ batteries are used to provide power for an air deployable expendable store "PHOTO FINISH". This report presents results of a test program to determine if the system is safe for Fleet use.

Approved by:

Jack R. Dixon
 JACK R. DIXON, Head
 Materials Division



Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

CONTENTS

<u>Chapter</u>		<u>Page</u>
1	INTRODUCTION.....	1-1
2	EXPERIMENTAL.....	2-1
3	RESULTS AND DISCUSSION.....	3-1
4	CONCLUSIONS.....	4-1

ILLUSTRATIONS

<u>Figure</u>		<u>Page</u>
1	SCHEMATIC OF "PHOTO FINISH" SHOWING LOCATION OF THERMOCOUPLES AND PRESSURE TRANSDUCER AS POSITIONED FOR TEST.....	2-2
2	PHOTOGRAPH OF BATTERY PACKAGE. THE POWER SUPPLIES USED TO POWER "PHOTO FINISH" ARE CONTAINED INSIDE THIS PACKAGE.....	2-3
3	SHORT CIRCUIT OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. SHORT CIRCUIT CURRENT AND BATTERY VOLTAGES ARE INDICATED FOR EACH BATTERY. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.....	3-2
4	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.....	3-4
5	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.....	3-5
6	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.....	3-6
7	SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN. THE ENTIRE "PHOTO FINISH" UNIT WAS PRECONDITIONED AT 71°C PRIOR TO DISCHARGE.....	3-7

ILLUSTRATIONS (Cont.)

<u>Figure</u>		<u>Page</u>
8	PHOTOGRAPH OF "PHOTO FINISH" UNIT WITH HEAT TAPE IN VICINITY OF BATTERY PACK.....	3-10
9	RESULTS OF EXTERNAL HEATING OF "PHOTO FINISH". THE BATTERY WAS HEATED AT APPROXIMATELY 10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED.....	3-11
10	RESULTS OF EXTERNAL HEATING OF "PHOTO FINISH". THE BATTERY WAS HEATED AT APPROXIMATELY 10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED.....	3-12

TABLES

<u>Table</u>		<u>Page</u>
1	SUMMARY OF SHORT CIRCUIT DATA ON "PHOTO FINISH" (THROUGH 0.4 OHM LOAD).....	3-3
2	CAPACITY (IN AMPERE HOURS) OF "PHOTO FINISH" BATTERIES TO A 2 VOLT/CELL CUTOFF.....	3-8
3	MEASURED VELOCITY AT WHICH NOSE CAP WAS EJECTED. MAXIMUM PRESSURES ARE ALSO SUMMARIZED.....	3-9

CHAPTER 1

INTRODUCTION

A technical evaluation and safety analysis has been conducted on an air-deployable expendable store "PHOTO FINISH". The purpose of this report is to describe the results of a test program requested by NAVELEX (as required by reference 1) and conducted by the Naval Surface Weapons Center. The tests were conducted to determine if the unit was safe to handle, ship, and deploy as configured.

Abuse conditions were generated by:

1. Simultaneous short circuiting of the batteries with all fuses bypassed.
2. Simultaneous discharge of each battery pack into voltage reversal with an external D.C. constant current power supply. Discharge currents were equal to the fuse value of each battery in the pack.
3. Heating of the batteries to 500°C at a rate of 20°C/min.

"PHOTO FINISH" is composed of four separate batteries described below:

1. Battery number one has thirteen L026SH lithium sulfur dioxide cells wired in series.
2. Battery number two has four L026SH lithium sulfur dioxide cells wired in series.
3. Batteries three and four each have two L032S lithium sulfur dioxide cells wired in series.

All cells used in this test program were manufactured by Duracell International, Inc.

Batteries one and two each have a thermal fuse (80-90°C) and a four ampere fuse in the ground leg. Batteries three and four each have a three ampere fuse in the ground leg. This combination of fuses protects against short circuit and excessive discharge rates.

¹NAVSEAINST 9310.1, March 1979.

CHAPTER 2

EXPERIMENTAL

The experimental program was conducted as follows:

1. The four batteries of the pack were simultaneously short-circuited inside the "PHOTO FINISH" housing with all fuses bypassed. Voltages, currents, temperatures, and pressures were monitored throughout the run. This test was repeated three times.
2. The four batteries of the pack were simultaneously discharged at the fuse values with an external D.C. constant current power supply. For example, batteries one and two were discharged at four amperes, and batteries three and four at three amperes. Three discharges were carried out at ambient temperatures (10-25°C) and one with the buoy preheated to 71°C. Voltages, temperatures, and pressures were monitored throughout the run.
3. The third set of tests conducted was external heating of the battery pack by wrapping heat tape around the "PHOTO FINISH" unit in the vicinity of the battery pack.

Pressures were measured using a Standard Controls Model Number 1200-41-1 pressure transducer. Type K thermocouples were used to measure the temperatures at several points on the package containing the four batteries. Thermocouple location on the complete battery package and "PHOTO FINISH" housing is indicated in Figure 1. A photograph of the battery package is shown in Figure 2.

Video tapes and high speed movies were made on all tests and are on file at the Naval Surface Weapons Center, White Oak.




FIGURE 1 SCHEMATIC OF "PHOTO FINISH" SHOWING LOCATION OF THERMOCOUPLES AND PRESSURE TRANSDUCER AS POSITIONED FOR TEST.



FIGURE 2 PHOTOGRAPH OF BATTERY PACKAGE. THE POWER SUPPLIES USED TO POWER "PHOTO FINISH" ARE CONTAINED INSIDE THIS PACKAGE.

CHAPTER 3

RESULTS AND DISCUSSION

The first series of tests was simultaneous short-circuiting of all four batteries within the pack (all fuses bypassed) through 0.4 ohm loads. The above test was repeated three times. All three tests resulted in venting of the batteries. However, the first two tests resulted in low housing pressure upon venting. A post mortem of these units indicated that the housing leaked where the thermocouples and voltage leads exited the unit. The problem was corrected and a third short circuit test was run. The results of the third run are presented in Figure 3. Maximum pressure observed is 11 psig. The ventings caused the nose cap to be ejected at approximately 10 ft/sec. This velocity was measured using high speed photography and video techniques. After nose cap ejection the float bag inflated and subsequently burst. A summary of the short circuit data is presented in Table 1.

The second series of tests was simultaneous discharge of the four batteries at the fuse value using four D.C. power supplies. As in short circuit, all fuses were bypassed. Batteries one and two had thirteen and four L026SH cells in series respectively. Batteries three and four each had two L032S cells in series. Batteries one and two were discharged at four amperes while three and four were discharged at three amperes. All discharges took place at room temperature except for discharge 033001 where the buoy was preconditioned at 71°C. The results are presented in Figures 4-7. A summary of the capacities observed along with the maximum temperature observed are presented in Table 2. All four tests resulted in nose cap ejection and float bag rupture. Batteries three and four were the first to vent. In all cases the venting of batteries three and four caused the housing pressure to increase to five psig. Nose cap ejection only occurred when batteries one and two vented. A summary of the pressure and nose cap ejection velocities is presented in Table 3.

The last series of tests conducted was external heating of the battery pack by wrapping heat tape around the "PHOTO FINISH" unit in the vicinity of the battery pack. A photograph of "PHOTO FINISH" with the heat tape in place is shown in Figure 8. As in the previous tests, all fuses were bypassed. This test was repeated. The results of the heating test are presented in Figures 9 and 10. External heating forced the batteries to vent and caused a nose cap ejection similar to short circuit and constant current discharge.




FIGURE 3 SHORT CIRCUIT OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. SHORT CIRCUIT CURRENT AND BATTERY VOLTAGES ARE INDICATED FOR EACH BATTERY. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.

TABLE 1 SUMMARY OF SHORT CIRCUIT DATA
ON "PHOTO FINISH" THROUGH 0.4 OHM LOAD

<u>TEST NUMBER</u>	<u>BATTERY NUMBER AND MAXIMUM CURRENT</u>				<u>MAXIMUM</u> <u>BATTERY PACK</u> <u>TEMPERATURE (°C)</u>
	1	2	3	4	
224001	53.4	12.2	9.0	6.2	--
224002	54.0	14.0	6.0	6.0	110
032001	40.5	17.5	7.5	7.0	267




FIGURE 4 SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.




FIGURE 5 SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.





FIGURE 6 SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN.



NSWC TR 81-327

FIGURE 7 SIMULTANEOUS CONSTANT CURRENT DISCHARGE OF ALL FOUR "PHOTO FINISH" BATTERY SUPPLIES. BATTERIES ONE AND TWO WERE DISCHARGED AT FOUR AMPERES WHILE THREE AND FOUR WERE DISCHARGED AT THREE AMPERES CONSTANT CURRENT. HOUSING PRESSURE AND BATTERY PACK TEMPERATURE ARE ALSO SHOWN. THE ENTIRE "PHOTO FINISH" UNIT WAS PRECONDITIONED AT 71°C PRIOR TO DISCHARGE.

TABLE 2 CAPACITY IN AMPERE HOURS OF "PHOTO FINISH"
BATTERIES TO A 2 VOLT/CELL CUTOFF

<u>TEST NUMBER</u>	<u>BATTERY NUMBER AND CAPACITY</u>				<u>MAXIMUM BATTERY PACK TEMPERATURE (°C)</u>
	<u>1</u>	<u>2</u>	<u>3</u>	<u>4</u>	
226001	3.05	3.30	0	0	291
227001	5.60	5.67	0.3	0.3	152
227002	5.03	5.03	0.12	0.12	605
033001	4.27	4.53	0.13	0.13	814

TABLE 3 MEASURED VELOCITY AT WHICH NOSE CAP WAS EJECTED.
 MAXIMUM PRESSURES ARE ALSO SUMMARIZED

<u>TEST NUMBER</u>	<u>MEASURED VELOCITY (IN FT/SEC) AT 1' AND 8'</u>		<u>MAXIMUM PRESSURE (psig)</u>
	<u>1'</u>	<u>and 8'</u>	
225001	--	--	23.0
226001	--	--	11.0
227001	24	20	23.0
227002	16	12	14.9
032001	10	--	11.0
032002	24	19	30.0
033001	4	--	12.0




FIGURE 8 PHOTOGRAPH OF "PHOTO FINISH" UNIT WITH HEAT TAPE IN VICINITY OF BATTERY PACK




FIGURE 9 RESULTS OF EXTERNAL HEATING OF "PHOTO FINISH". THE BATTERY WAS HEATED AT APPROXIMATELY 10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED.




FIGURE 10 RESULTS OF EXTERNAL HEATING OF "PHOTO FINISH". THE BATTERY WAS HEATED AT APPROXIMATELY 10°C/MINUTE. BATTERY TEMPERATURE, VOLTAGES OF EACH BATTERY AND HOUSING PRESSURE ARE PLOTTED.

CHAPTER 4

CONCLUSIONS

The tests results presented in this report indicate that nose cap ejection will take place under "worst case" conditions. However, no fires were observed under any of the tests conducted.

Based upon the tests results and the scenario of use, the following recommendations should enhance the safety of "PHOTO FINISH" units:

1. Label the batteries in accordance with reference 1.
2. Reduce the three ampere fuse in batteries three and four to approximately one ampere.
3. Store batteries separately from the "PHOTO FINISH" units until ninety days prior to deployment.
4. After the batteries are loaded into the units, a CAUTION label in accordance with Figure 1 of reference (1) should be placed on both the unit and the grey overpack.
5. Do not remove units from grey overpack greater than fifteen days prior to deployment.
6. A warning notice to handling personnel should be placed on the units that after the batteries are loaded, a possibility exists for nose cap ejection.
7. The "PHOTO FINISH" units are to be loaded into the launch tubes only, and not stored inside the aircraft.

DISTRIBUTION

	<u>Copies</u>		<u>Copies</u>
Defense Technical Information Center		Commander	
Cameron Station		Naval Weapons Center	
Alexandria, VA 22314	12	Attn: Code 38 (E. Royce)	1
		Code 3352 (A. Fletcher)	1
Commander		Mr. L. Pracchia	1
Naval Sea Systems Command		China Lake, CA 93555	
Attn: SEA 06R (D. J. Pastine)	1	Office of Naval Research	
SEA 63R3 (F. Romano)	1	Attn: ONR 472 (G. Neece)	1
SEA 9823	1	ONR 472 (J. Smith)	1
SEA 06H (E. Daugherty)	2	800 N. Quincy Street	
SEA 09G32	2	Arlington, VA 22217	
SEA 921AN		Commander	
(LCDR K. A. Tobin)	1	Naval Weapons Support Center	
NAVSEA 543	1	Electrochemical Power Sources Division	
Washington, DC 20362		Attn: Code 305 (M. Robertson)	1
Commander		Code 3061 (S. Shuler)	1
Naval Ocean Systems Center		Crane, IN 47522	
Attn: Code 922	1	Commander	
Code 712 (J. McCartney)	1	Naval Electronics Systems Command	
Code 6343 (S. Spazk)	1	Attn: Code PME 124-31	
San Diego, CA 92152		(A. H. Sobel)	1
Commander		NAVELEX 01K (A. Sliwa)	1
Naval Intelligence Support Center		40736 (W. J. Weingartner)	1
Attn: Code 362 (H. Ruskie)	1	Washington, DC 20360	
Washington, DC 20390		Commander	
Office of Navy Technology		Naval Air Development Center	
Associate Director		Attn: Library	1
Attn: Support Technology (072)	1	Warminster, PA 18974	
800 N. Quincy Street		Commander	
Arlington, VA 22217		Naval Underwater Systems Center	
Chief of Naval Operations		Attn: Code 3642 (R. Lazar)	2
Operating Evaluation Group	1	(J. Moden)	
Washington, DC 20350		Newport, RI 02840	

DISTRIBUTION (Cont.)

	<u>Copies</u>		<u>Copies</u>
David W. Taylor Naval Ship Research and Development Center Annapolis Laboratory Attn: Code 2724 (H. R. Urbach) Annapolis, MD 21401	1	Honeywell Inc. Defense Systems Division Power Sources Center Attn: Library 104 Rock Road Horsham, PA 19044	1
U. S. Army HQDA-DAEN-ASR-SL Attn: Charles Sculla Washington, DC 20314	1	Yardney Electric Corporation Attn: Library 82 Mechanic Street Pawcatuck, CT 02891	1
U. S. Army Electronics Command Attn: Code DELET-P (T. Reiss) Code DRSEL-TR-PR (Dr. S. Gilman) Fort Monmouth, NJ 07703	1	Duracell International Attn: B. McDonald South Broadway Taerytown, NY 10591	1
Air Force Aero Propulsion Lab Attn: AFAPL/OPE-1 (W. Bishop) (D. Marsh)	1	Duracell International Laboratory for Physical Science Attn: Library Burlington, MA 01803	1
Wright-Patterson AFB, OH 45433	1		
Headquarters Department of Transportation U. S. Coast Guard Ocean Engineering Division Attn: GEOE-3/61 (R. Potter) Washington, DC 20590	1	Power Conversion Inc. 70 MacQuesten Parkway South Mount Vernon, NY 10550	1
NASA Goddard Space Flight Center Attn: Code 711 (G. Halpert) Hampton, VA 23665	1	Eagle-Picher Industries Couples Department Attn: Library Joplin, MO 64801	1
NASA Johnson Space Center NASA Rd 1 Attn: Code EP5 (B. J. Bragg) Houston, TX 77058	1	Sparton Electronics Attn: Carroll H. Bush 2400 East Ganson Street Jackson, MI 49202	1
Lockheed Palo Alto Research Laboratory Lockheed Missile & Space Co., Inc. Attn: Library 3251 Hanover Street Palo Alto, CA 94304	1	Sonatech Inc. Attn: Reggie Sear 700 Francis Botello Road Goleta, CA 93017	1
Altus Corporation 1610 Crane Court San Jose, CA 95112	1	Sanders Associates, Inc. Attn: George Disco 95 Canal Street Nashua, NH 03061	1

DISTRIBUTION (Cont.)

	<u>Copies</u>		<u>Copies</u>
Electrochem Industries, Inc. Attn: Dr. Robert Murphy 9990 Wehrle Drive Clarence, NY 14031	1	McDonnell Douglas Corporation 1150 17th Street, N.W., Suite 500 Washington, DC 20036	1
Magnavox Company Department 529 Attn: Carl Keuneke 1313 Production Road Fort Wayne, IN 46808	1	EIC Corporation Attn: Dr. K. M. Abraham 55 Chapel Street Newton, MA 02158	1
Ray-O-Vac Attn: R. F. Udell B. C. Bergum 101 East Washington Avenue Madison, WI 53703	1 1	General Electric Co. Attn: Dr. R. W. Race, Manager Advance Programs Marketing Room 2544A - OP#2 100 Plastics Avenue Pittsfield, MA 01201	1 1
Gould, Inc. Gould Laboratories 40 Gould Center Rolling Meadows, IL 60000	1	Norton Air Force Base Attn: Code BMO/ENBE (Capt. A. S. Alanis) Code AFISC/SES Norton AFB, CA 92409	1 1
The Boeing Company Attn: Dr. A. C. Johnson P. O. Box 3707 Seattle, WN 98124	1	Honeywell Power Sources Center Attn: Dr. David L. Chua 104 Rock Road Horsham, PA 19044	
GTE Laboratories, Inc. Attn: Library 40 Sylvan Road Waltham, MA 02154	1	Battery Engineering Attn: Dr. N. Marincic 80 Oak Street Newton, MA 02164	1
Martin Marietta Aerospace Attn: John W. Wear P.O. Box 179 Denver, CO 80201	1	NOAA Data Buoy Center Attn: Mr. D. Scully NSTL STATION, MS 39529	1
GTE Sylvania Attn: Dr. Robert McDonald 189 B Street Needham Heights, MA 02194	1	Teledyne Electronics Attn: Mr. G. Lamb 649 Lawrence Drive Newbury Park, CA 91320	1
Navy Environmental Health Center Attn: J. R. Crawl, Head Hazardous Mat. Eval Br. Naval Station Norfolk, VA 23511	1	Mare Island Naval Ship Yard Attn: Code 280.08 Stop 060 (R. Houlder) Vallejo, CA 94592	1

DISTRIBUTION (Cont.)

	<u>Copies</u>		<u>Copies</u>
The Aerospace Corporation		Acoustic Systems, Inc.	
Attn: Mr. Albert Heller	1	Attn: Dr. James Fish	1
2350 East El Segundo Blvd.		600 Norman Firestone Rd.	
P. O. Box 92957		Goleta, CA 93117	
Los Angeles, CA 90009			
 <u>Internal Distribution:</u>			
R30	1		
R33	1		
R33 (Bis)	70		
E35	1		
E431	9		
E432	3		